

Teledyne Reynolds, Inc.
5005 McConnell Avenue
Los Angeles, CA 90066

January 25, 2010

To: **Teledyne Reynolds Suppliers**

Subject: **Revised Supplier Quality Assurance Provision (SQAP) Codes**

Effective this date, revised form QSF-106-8, Supplier Quality Assurance Provisions (Replaces SQAP-100), dated 01-25-10, is in effect. Changes in the new revision include:

SQAP Code 01: 1) Now includes general provisions that were noted in Table 1 of the previous version of QSF-106-8. The previous Code 01 has also been folded into the requirements.

2) Counterfeit Parts and Materials are now addressed as follows:

“The supplier shall verify the procurement source and associated certifying paperwork. Appropriate incoming inspection test methods shall be used to detect potential counterfeit parts and materials. The supplier shall flow this requirement down to all sub-tier suppliers to prevent the inadvertent use of counterfeit parts and materials.”

3) RoHS Compliance is now addressed as follows:

“As stated in the European Union’s Restriction on Hazardous Substances (RoHS) Directive 2002/95/EC, **materials provided to TRI must not contain more than 0.1% weight lead, mercury (or compounds thereof), hexavalent chromium, polybrominated biphenyls (PBB), and polybrominated diphenyl ethers (PBDE); and 0.01 % weight cadmium (or compounds thereof).** If materials do not comply with the restrictions noted, the supplier shall notify TRI Purchasing for direction prior to acceptance of order or shipment.”

SQAP Code 99: Requires supplier submission of first article when imposed. First articles may also be imposed via line items on the purchase order.

QSF-106-8 is posted electronically in the “Supplier Portal” folder at www.teledynereynolds.com. Unless otherwise specified in the Teledyne Reynolds purchase order, suppliers will be responsible for compliance to the revision date of QSF-106-8 in effect on the date of the Teledyne Reynolds purchase order. If you do not have a current version, please contact your TRI Purchasing representative.

Thank you in advance for your cooperation and continued support!



Steve Thompson
Director, Quality Assurance
(310) 823-5491, X261
sthompson@teledyne.com

cc:

M. Centeno
J. Arroyo
S. Matthews
J. Perez
N. Kiyani
H. Lam
R. Montalvo